
## **GS & TJ Services** Property Inspection Report



## 32063100310000 10/15/2007

1234 Main Street, Flossmoor IL, 60422 Inspection prepared for: Client Leon Inspection Date: 7/19/2012 Time: 11:00am Age: 58 yrs Size: 1,930 sq ft

Inspector: Leon Slack III License # 450.010693 Chicago, IL 60628 Phone: 773-234-4785 Fax: 773-584-0904

Email: inspectors@GSandTJservices.com www.illinoisinspectors.com



Full color photos is an added feature of our inspections to help you identify and understand problems. If you need any assistance in understanding portions of report, please contact me.

#### **Report Summary**

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expenses to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all of the pages of the report as the summary alone does not explain all the issues. All repairs must be done by a licensed &bonded trade or profession. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

#### Bedrooms

Page 9 Item: 12	Wall Condition	<ul> <li>There is evidence of moisture entering structure.</li> </ul>

1234 Main Street, Flossmoor, IL

# **Inspection Details**

#### 1. Attendance

In Attendance: Client present

#### 2. Home Type

Home Type: Single Family Home - Brick and Frame structure

#### 3. Occupancy

Occupancy: Vacant

#### **Interior Areas**

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

1. Bar Good Fair Poor N/A None X
2. Cabinets Good Fair Poor N/A None X
3. Ceiling Good Fair Poor N/A None X Drywall ceilings noted
4. Ceiling Fans
5. Closets
Good       Fair       Poor       N/A       None         X       Image: N/A       Observations:       Image: Observation of the steed         • Operated normally when tested.

Page 3 of 57

## 1234 Main Street, Flossmoor, IL

7. Doors
Good     Fair     Poor     N/A     None       X     I     I     I
East dow cill acced as dition
Front door sill - good condition
8. Electrical         Good       Fair       Poor       N/A       None         X       I       I       I       I
9. Floor
Good       Fair       Poor       N/A       None         X          Observations:         • Hardware floor noted
Hardwood floor living/dining room
10. Security Bars
Good Fair Poor N/A None

Page 4 of 57

11. Smoke Detectors         Good       Fair       Poor       N/A       None         X       Observations:       • Operated when tested
12. Stairs & Handrail
13. Window-Wall AC or Heat
14. Window Condition
Good Fair Poor N/A None X Materials: Vinyl framed double hung window noted.
Living/dining room windows
15. Ceiling Condition
$\begin{array}{c c} \hline & & \\ \hline \hline & & \\ \hline \hline & & \\ \hline & & \\ \hline & & \\ \hline \hline \\ \hline & & \\ \hline \hline \\ \hline \\$
16. Patio Doors         Good Fair Poor N/A None         X       X
17. Screen Doors       Good     Fair       X     None
18. Wall Condition
Good Fair Poor N/A None X Materials: Drywall walls noted.

None

## 1234 Main Street, Flossmoor, IL

#### 19. Fireplace

Good	Fair	Poor	N/A
X			

Materials: Living Room Materials: Masonry fireplace noted.



Fireplace damper handle

Some Fireplace brick deterioration

#### Bedrooms

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

#### 1. Locations


Locations: Front Bedroom #1 • Middle bedroom #2 • Rear Bedroom #3 2. Bar Good Fair N/A Poor None Х 3. Cabinets Good Fair Poor N/A None Х 4. Ceiling Fans Good Fair Poor N/A None **Observations:** Х • Operated normally when tested, at time of inspection. Master bedroom ceiling fan Bedroom ceiling fan 5. Closets Fair Good Poor N/A None Observations: Х • The closet is in serviceable condition.

#### 6. Doors




#### 7. Electrical






### 1234 Main Street, Flossmoor, IL





Page 9 of 57




### 1234 Main Street, Flossmoor, IL

#### Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

#### 1. Cabinets



#### 2. Counters





Granite appearance countertop

3. Dishwasher
Good       Fair       Poor       N/A       None         X         Observations:         • operated
4. Doors
Good       Fair       Poor       N/A       None         X       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Y       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A
5. Garbage Disposal
Good Fair Poor N/A None
6. Microwave
Good       Fair       Poor       NA       None         X       Image: Second Secon

## 1234 Main Street, Flossmoor, IL



### 7. Cook top condition

Good	Fair	Poor	N/A	None	
Х					Observations: • Gas cook top noted.
					• All heating elements operated when tested.





Observations: • Oven: gas burners

Page 12 of 57

### 1234 Main Street, Flossmoor, IL



• Recirculator only. Exterior vented fans are generally suggested when gas range in place.

12. \	Winc	dow (	Cond	dition	
Good	Fair	Poor	N/A	None	Materials: Vinyl framed double hung window noted.
			1	ļ	

Page 13 of 57



## 1234 Main Street, Flossmoor, IL

16. Security Bars
Good Fair Poor N/A None
17. Patio Doors
Good Fair Poor N/A None
18. Screen Doors Good Fair Poor N/A None
Good Fair Poor N/A None
19. Electrical
X Poor N/A None Observations: • No major system safety or function concerns noted at time of inspection.
20. GFCI
X Fair Poor N/A None Observations: • GFCI in place and operational
21. Wall Condition
X Poor N/A None Materials: Drywall walls noted.
22. Refrigerator
Materials: Appears in operable condition. Temperature tested. Freezer 4 degrees. Fridge 37 degrees
23. Backsplash condition
Good Fair Poor N/A None

## 1234 Main Street, Flossmoor, IL

#### 24. Backsplash Good Fair Poor N/A

ood Fair Poor N/A

None X

#### 25. Refrigerator

Good	Fair Poor N/A	Observations: • Tested ice cubes a	and crushed ice d	ispensers	
		and the second s			
		A STATES			

Testing ice maker

Page 16 of 57

#### Heat/AC

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

1. Combustion					
Good	Fair	Poor	N/A	None	
Х					

## 2. Heater Condition



Materials: The furnace is located in utility room Materials: Gas fired forced hot air



Power switch


burner test

#### 3. Heater Base

N/A



Observations: • The heater base appears to be functional.



Page 17 of 57

### 1234 Main Street, Flossmoor, IL



#### 6. Venting



### 7. Gas Valves

Good	Fair	Poor
х		

N/A None Observations:

• Gas shut off valves were present and functional.

#### 8. Refrigerant Lines

Good	Fair	Poor	N/A	None	
Х					Observations: • No defects found.

#### 9. AC Compress Condition

	Good	Fair	Poor	N/A	None	. ~
I						ľ
I	Х					
1						

Compressor Type: electric

Location: The compressor is located on the exterior grounds.


### Observations:

• Appeared functional at the time of inspection.




Like new

### 1234 Main Street, Flossmoor, IL



Page 19 of 57



Programmable thermostat


### 1234 Main Street, Flossmoor, IL



### 1234 Main Street, Flossmoor, IL




#### 5. Water Heater Condition



• Tank appears to be in satisfactory condition -- no concerns.



Like new water heater and expansion tank




Page 22 of 57


## 1234 Main Street, Flossmoor, IL

9. Plumbing         Good       Fair       Poor       N/A       None         X       A       A       A       A         Observations:       • No deficiencies observed at the visible portions of the supply piping.
10. Overflow Condition
Good       Fair       Poor       N/A       None         X       I       I       I       I
11. Strapping
Good Fair Poor N/A None

### 1234 Main Street, Flossmoor, IL



### 1234 Main Street, Flossmoor, IL



Page 25 of 57

## 1234 Main Street, Flossmoor, IL


6. Electrical
Good     Fair     Poor     N/A     None       X
7. Exterior Door
Good     Fair     Poor     N/A     None       X
8. Fire Door
Good Fair Poor N/A None
9. Garage Door Condition
Good       Fair       Poor       N/A       None         X       A       A       A       A         Observations:       • No deficiencies observed.
10. Garage Door Parts
Good       Fair       Poor       N/A       None         X       Observations:       • The garage door appeared functional during the inspection.
11. Garage Opener Status
Good       Fair       Poor       N/A       None         X         Observations:       • Chain drive opener noted.

## 1234 Main Street, Flossmoor, IL

<image/> <image/>
12. Garage Door's Reverse Status         Good       Fair       Poor       N/A       None         X       Source       Observations:       • Garage vehicle door auto-reverse is inoperable.         • Eye beam system present and operating.
13. Ventilation
Good       Fair       Poor       N/A       None         X       Image: Second Seco
14. Vent Screens
X Poor N/A None Observations: • Vent screens noted as functional.
15. Cabinets
Good Fair Poor N/A None
16. Counters
Good Fair Poor N/A None
17. Wash Basin
Good Fair Poor N/A None

Page 27 of 57

### 1234 Main Street, Flossmoor, IL




Page 28 of 57

## 1234 Main Street, Flossmoor, IL



## 3. Breakers in off position



#### 4. Cable Feeds

Good	Fair	Poor	N/A	None	
					Observations:
	×				• There is an overhead service drop noted.



Overhead mast three wire (240 volt) system

5. Breakers	
Good       Fair       Poor       N/A       None         X       Observations:       • All of the circuit breakers appeared serviceable.	
6. Fuses	
Good Fair Poor N/A None	
7. Subpanel	

Page 29 of 57

#### 8. Electrical Service

#### 9. Electrical Service





**Electrical meter** 

### 1234 Main Street, Flossmoor, IL



Page 31 of 57

### 1234 Main Street, Flossmoor, IL





Flashing wear near chimney - suggest year maintenance

#### 3. Chimney

 Good
 Fair
 Poor
 N/A
 None
 Observations:

 X

• No major system safety or function concerns noted at time of inspection.



Firepace Chimney cap

Page 32 of 57

## 1234 Main Street, Flossmoor, IL



#### Furnace chimney cap

4. Sky Lights
5. Spark Arrestor Good Fair Poor N/A None X
6. Vent Caps Good Fair Poor N/A None X Observations: • The vent cap is rusted.
7. Gutter
X Observations: • No major system safety or function concerns noted at time of inspection.




Some asphalt sand in gutter, indicative of recent roofing


Page 34 of 57

## 1234 Main Street, Flossmoor, IL

Attic
1. Access Good Fair Poor N/A None CL
X Observations: • Attic light located just inside access • Access in utility/laundry room
2. Structure
Good       Fair       Poor       N/A       None         X       Image: N/A       Image: N
Evidence of past moisture
<ul> <li>3. Ventilation</li> <li>Good Fair Poor N/A None</li> <li>Observations:</li> <li>Under eave soffit inlet vents noted.</li> <li>Fixed, roof-field exhaust vent noted.</li> </ul>
4. Vent Screens         Good       Fair       Poor       N/A       None         X       I       I       I       I
5. Duct Work           Good         Fair         Poor         N/A         None           X         Image: Solution of the second
6. Electrical
7. Attic Plumbing
Good       Fair       Poor       N/A       None         X
Page 35 of 57

# 1234 Main Street, Flossmoor, IL





Brick siding left (west) side

Wood siding on front

Page 37 of 57



Vinyl siding of addition sunroom

Wood siding on front side of building



Suggest sealing patches to prevent moisture intrusion

#### 4. Eaves & Facia



Page 38 of 57

### 1234 Main Street, Flossmoor, IL



Eaves with ventilation

#### 5. Exterior Paint




#### 6. Stucco



#### 7. Downspouts Good Fair Poor N/A



Observations:



• Downspouts with missing extention. Rain water deposited near foundation, causing water intrusion into basement



Extended downspout at front left (southwest)



Suggest extending downspout to deposit water away from building



Downspout in rear appears to be blocked. Suggest opening up to deposit away from building

#### 8. Exterior Outlets

Good	Fair	Poor	N/A	None
Х				



Testing exterior outlets

#### 9. Brick condition

Good	Fair	Poor	N/A	None	
Х					

# 1234 Main Street, Flossmoor, IL

Foundation
1. Slab Foundation
Good       Fair       Poor       N/A       None         X       Observations:       • Concrete slab not visible due to floor coverings.
2. Foundation Perimeter
Good       Fair       Poor       N/A       None         X       Observations:       • Visible portions of foundation wall were dry at the time of the inspection.
3. Foundation Walls
Good       Fair       Poor       N/A       None         X       Observations:       • normal settlement
4. Cripple Walls
Good       Fair       Poor       N/A       None         Image: A structure of the s
5. Ventilation
Good       Fair       Poor       N/A       None         Image:
6. Vent Screens
Good Fair Poor N/A None
7. Access Panel
Good Fair Poor N/A None
8. Post and Girders
Good     Fair     Poor     N/A     None       Image: State Stat
9. Sub Flooring
Good Fair Poor N/A None
10. Anchor Bolts
Good Fair Poor N/A None X Deservations: • The anchor bolts were not visible.
11. Foundation Electrical
Good     Fair     Poor     N/A     None       Image:
12. Foundation Plumbing
Good Fair Poor N/A None Observations: X • Not determined
Page 41 of 57

# 1234 Main Street, Flossmoor, IL


#### 13. Sump Pump Good Fair Poor N/A



#### 14. Ducting


Good	Fair	Poor	N/A	None
			Х	

Page 42 of 57



Page 43 of 57

### 1234 Main Street, Flossmoor, IL



Like new frost free faucet

Materials: Wood

8. Fence Condition

Poor

N/A

None

Fair


Х

Good

Testing water pressure

Fence appears to be recently installed

### 1234 Main Street, Flossmoor, IL



because of the direct and indirect damage that moisture can have on the foundation. It is very important, therefore, that surface runoff water be adequately diverted away from the home. Lot grading should slope away and fall a minimum of one (1) inch every foot for a distance of six (6) feet around the perimeter of the building.




Front graded generally away from foundation

Left (west) side sidewalk graded towards house

### 1234 Main Street, Flossmoor, IL

### GS & TJ Services



### 1234 Main Street, Flossmoor, IL



Suggesting keeping trimmed from exterior wall

Back yard grass. It appears that some sod did not take

19. Water Pressure
Good Fair Poor N/A None Observations:
X • 45
20. Pressure Regulator
X Observations: • Pressure regulator noted.

	05511001, 11
Water	
1. Water Service	
Good       Fair       Poor       N/A       None         X       Image: A state of the	

# 1234 Main Street, Flossmoor, IL


1st floor Bathroom
1. Locations
Locations: Master Bathroom • 2nd bathroom
2. Cabinets
X Deservations: No deficiencies observed.
3. Ceiling Condition
X None Materials: There are drywall ceilings noted.
4. Counters
Good       Fair       Poor       N/A       None         X         Observations:         • No discrepancies noted.
5. Doors
Good       Fair       Poor       N/A       None         X       Image: N/A       Image: N/A       Image: N/A       Image: N/A         V       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A       Image: N/A         Image: N/A       Image: N/A       <
6. Electrical
Good       Fair       Poor       N/A       None         X       Observations:       • No major system safety or function concerns noted at time of inspection.
7. GFCI
Good       Fair       Poor       N/A       None         X       Observations:       • GFCI in place and operational
8. Exhaust Fan
Good       Fair       Poor       N/A       None         X       Image: Second Hair Poor       N/A       Image: Second Hair Poor       Image: Second Hair Poor         Y       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor         Y       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor         Y       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor         X       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor         X       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor         X       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Hair Poor         X       Image: Second Hair Poor         X       Image: Second Hair Poor         X       Image: Second Hair Poor       Image: Second Hair Poor       Image: Second Ha
Exhaust fan and light

# 1234 Main Street, Flossmoor, IL

9. Floor Condition
X       Image: Coord Fair Poor N/A None         Good Fair Poor N/A None       Observations:         X       Image: Coord Poor N/A None         Observations:       Observations:         • Central heating and cooling noted in this room. At the time of the inspection, all appeared to be functioning and in serviceable condition.
11. Lighting Good Fair Poor N/A None X None
Good     Fair     Poor     N/A     None       X     I     I     I
1st floor Bathroom Mirrors
13. Plumbing       Good     Fair       Y     None
14. Security Bars         Good Fair Poor N/A None         Good       Fair       Poor       N/A       None         X       X       X       X
Good       Fair       Poor       N/A       None         X       Image: N/A       Observations:       • functional


Page 51 of 57

### 1234 Main Street, Flossmoor, IL



Page 52 of 57

## 1234 Main Street, Flossmoor, IL



# 1234 Main Street, Flossmoor, IL

### 22. Wall condition





Page 55 of 57

# 1234 Main Street, Flossmoor, IL

6. Electrical Good Fair Poor N/A None X Deservations: • No major system safety or function concerns noted at time of inspection.
7. GFCI         Good       Fair       Poor       N/A       None         X       Observations:       • GFCI in place and operational
8. Floor Condition Good Fair Poor N/A None X Materials: Ceramic tile is noted.
9. Lighting       Good     Fair     Poor     N/A     None       X
10. Plumbing Good Fair Poor N/A None X
Hot cold and waste
11. Window Condition
12. Wall condition       Good     Fair       X     None
13. Wash basin Good Fair Poor N/A None X
Page 56 of 5

Page 56 of 57

15. Gas line Good Fair Poor

16. Floor drain

Х

N/A

N/A

None

None X

Dryer vent outside

# 1234 Main Street, Flossmoor, IL

Dryer vent ductwork

14. Drywer vent       Good     Fair       Y     N/A	
TI.III	Admiral I)
n I P	Land Key

### Page 57 of 57